

Week 8 Assessment:

1. Why was a Mate Connector specifically created in a Part Studio for the Bluetooth Speaker?
2. What does “Reorient Secondary Axis” mean, and when is it used?
3. What is Snap Mode, and why would it be used?
4. When is a Mate Group used?
5. Can replicate be used to mate across multiple parts, or only to multiple locations on the same part?